This brief provides a general overview of the **Safety Data Sheet** requirements in the Hazard Communication Standard OSHA's 29 CFR 1910.1200(g) and Appendix D of 29 CFR 1910.1200).

Section 1 ~ Identification						
Identity (As Used On Label and List)	Date Prepared:					
A1074W C&G White	10/16/2014					
Company Information: OMEGA INDUSTRIAL SUPPLY, INC	Emergency Telephone Number: 1-800-424-9300					
Address (Number, Street, Suite/Apt#) 101 Grobric Ct #1	Telephone Number for Information: 1-800-571-7347					
(City, State, and Zip Code) Fairfield, CA 94534	Signature of Prepare (Optional) REGULATORY DEPT.					

Section 2 ~ Hazard(s) Identification

Physical Hazards H229 - Pressurized container: May burst if heated Signal Word Warning

Health HazardsH315 - Causes skin irritationClassificationSkin irritation - Category 2Environmental HazardsN/AAerosol - Category 3OSHA Defined HazardsN/A

Label Elements

Response



Precautionary Statement General P101 - If medical advice is needed, have product container or label at hand.

P102 - Keep out of reach of children. P103 - Read label before use.

Precautionary Statement Prevention P264 - Wash thoroughly after handling.

P280 - Wear protective gloves/protective clothing/eye protection/face protection.

P210 - Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking.

P251 - Do not pierce or burn, even after use.

P302 + P352 - IF ON SKIN: Wash with plenty of soap and water. P332 + P313 - If skin irritation occurs: Get medical advice/attention.

P362 + P364 - Take off contaminated clothing and wash it before reuse. P410 - Protect from sunlight.

Storage P410 - Protect from sunlight.
P412 - Do not expose to temperatures exceeding 50 °C/122 °F.

Disposal N/A

Section 3 ~ Composition/Information on Ingredients

Components (Specific Chemical Identity, Common Name(s))	CAS No.	%(Wt.)
Methyl Siloxane Linear/Cyclic	70131-67-8	52% - 92%
Silica, Amorphous	7631-86-9	6% - 12%
Mineral Seal Oil	64742-46-7	2% - 4%
Methyltriacetoxysilane	4253-34-3	2% - 4%
Ethyltriacetoxysilane	17689-77-9	2% - 4%

Section 4 ~ First Aid Measures

Eyes - Remove source of exposure or move person to fresh air. Rinse eyes cautiously with lukewarm, gently flowing water for several minutes, while holding the eyelids open. Remove contact lenses, if present and easy to do. Continue rinsing for a duration of 15-20 minutes. Take care not to rinse contaminated water into the unaffected eye or onto the face. If eye irritation persists: Get medical advice/attention.

Inhalation - Remove source of exposure or move person to fresh air and keep comfortable for breathing. If exposed/feel unwell/concerned: Call a POISON CENTER/doctor. Eliminate all ignition sources if safe to do so.

Ingestion - Rinse mouth. Do NOT induce vomiting. Immediately call a POISON CENTER/doctor. If vomiting occurs naturally, lie on your side, in the recovery position. Never give anything by mouth to an unconscious or convulsing victim. Keep person warm and quiet.

Skin Contact - Take off immediately all contaminated clothing, shoes and leather goods (e.g. watchbands, belts). Gently blot or brush away excess product. Wash with plenty of lukewarm, gently flowing water for a duration of 15-20 minutes. Call a POISON CENTER/doctor if you feel unwell. Store contaminated clothing under water and wash before reuse or discard.

Section 5 ~ Fire Fighting Measures

Suitable Extinguishing Media – Use water, fog, dry chemical, or carbon dioxide. Carbon dioxide can displace oxygen. Use caution when applying carbon dioxide in confined spaces. Simultaneous use of foam and water on the same surface is to be avoided as water destroys the foam.

Unsuitable Extinguishing Media - Water may be ineffective but can be used to cool containers exposed to heat or flame.

Specific hazards arising from the chemical – Contents under pressure. Keep away from ignition sources and open flames. Exposure of containers to extreme heat and flames can cause them to rupture often with violent force.

Aerosol cans may rupture when heated.

Heated cans may burst.

In fire, will decompose to carbon dioxide, carbon monoxide

Special protective equipment and precautions for firefighters — Wear protective pressure self-contained breathing apparatus (SCBA) and full turnout gear. Care should always be exercised in dust/mist areas.

Fire-fighting procedures - N/A

Section 6 ~ Accidental Release Measures

Personal Precautions - ELIMINATE all ignition sources (no smoking, flares, sparks, or flames in immediate area). Use explosion proof equipment. Avoid breathing vapor. Avoid contact with skin, eye or clothing. Do not touch damaged containers or spilled materials unless wearing appropriate protective clothing.

Protective Equipment – Positive pressure, full-face piece self-contained breathing apparatus(SCBA), or positive pressure supplied air respirator with escape SCBA (NIOSH approved).

Emergency Procedures – Flammable/combustible material. ELIMINATE all ignition sources (no smoking, flares, sparks, or flames in immediate area). Stay upwind; keep out of low areas. Immediately turn off or isolate any source of ignition. Keep unnecessary people away; isolate hazard area and deny entry. Do not touch or walk through spilled material. Clean up immediately. Use absorbent sweeping compound to soak up material and put into suitable container for proper disposal.

 $\begin{tabular}{ll} \textbf{Methods and Materials For Containment And Cleaning } \textbf{Up} - N/A \\ \end{tabular}$

Environmental Precautions - Stop spill/release if it can be done safely. Prevent spilled material from entering sewers, storm drains, other unauthorized drainage systems and natural waterways by using sand, earth, or other appropriate barriers.

Section 7 ~ Handling and Storage

Precautions For Safe Handling - General: For industrial and institutional use only. For use by trained personnel only. Keep away from children. Wash hands after use. Do not get in eyes, on skin or on clothing. Do not breathe vapors or mists. Use good personal hygiene practices. Eating, drinking and smoking in work areas is prohibited. Remove contaminated clothing and protective equipment before entering eating areas. Eyewash stations and showers should be available in areas where this material is used and stored.

Storage Room Requirements: Keep container(s) tightly closed and properly labeled. Store in cool, dry, well-ventilated areas away from heat, direct sunlight and incompatibilities. Store in approved containers and protect against physical damage. Keep containers securely sealed when not in use. Indoor storage should meet OSHA standards and appropriate fire codes. Containers that have been opened must be carefully resealed to prevent leakage. Empty container retain residue and may be dangerous. Do not cut, drill, grind, weld, or perform similar operations on or near containers. Do not pressurize containers to empty them. Ground all structures, transfer containers and equipment to conform to the national electrical code. Use procedures that prevent static electrical sparks. Static electricity may accumulate and create a fire hazard. Store at temperatures below 120°F.

Ventilation Requirements: Use only with adequate ventilation to control air contaminants to their exposure limits. The use of local ventilation is recommended to

control emissions near the source

Section 8 ~ Exposure Controls/Personal Protection

Occupational Exposure Limits:

US. OSHA Table Z-1 Limits for Air Contaminants (29 CFR 1910.1000)

US. NIOSH: Pocket Guide to Chemical Hazards

Chemical Name	OSHA TWA	OSHA TWA	OSHA STEL	OSHA STEL	OSHA – Tables –	OSHA Carcinogen	OSHA Skin Designation	NIOSH TWA	NIOSH TWA	NIOSH STEL	NIOSH STEL	NIOSH Carcinogen
	(ppm)	(mg/m3)	(ppm)	(mg/m3)	Z1,2,3			(ppm)	(mg/m3)	(ppm)	(mg/m3)	
Mineral Seal Oil	500	2000			1							
Silica, Amorphous	20 (b)	80mg/m3 percent			1,3				6			
		SiO2+2										

Chemical Name	ACIH TWA (ppm)	ACGIH TWA (mg/m3)	ACGIH STEL (ppm)	ACGIH STEL (mg/m3)
Mineral Seal Oil				
Silica, Amorphous				

Respiratory Protection - If engineering controls do not maintain airborne concentrations to a level which is adequate to protect worker, a respiratory protection

program that meets or is equivalent to OSHA 29 CFR 1910.134 and ANSI Z88.2 should be followed. Check with respiratory protective

equipment suppliers. Where air-filtering respirators are suitable, select an appropriate combination of mask and filter. Select a filter suitable

for combined particulate/organic gases and vapors. When spraying more than one half can continuously or more than one can consecutively, use NIOSH approved respirator.

Skin Protection Other-Wear gloves, long sleeved shirt, long pants and other protective clothing as required to minimize skin contact.

Use of gloves approved to relevant standards made from the following materials may provide suitable chemical protection: PVC, neoprene

or nitrile rubber gloves. Suitability and durability of a glove is dependent on usage, e.g. frequency and duration of contact, chemical resistance of glove material, glove thickness, dexterity. Always seek advice from glove suppliers. Contaminated gloves should be replaced.

Chemical-resistant clothing is recommended to avoid prolonged contact. Avoid unnecessary skin contact.

Eye/face protection—Chemical goggles, safety glasses with side shields or vented/splash proof goggles. Contact lenses may absorb irritants. Particles may adhere to lenses and cause corneal

Section 9 ~ Physical Chemical Properties

Boiling Point	N/A	Specific Gravity	N/A
Vapor Pressure @ 70°F	N/A	Melting/Freezing Point	N/A
Vapor Density	Slower than ether	Evaporation Rate (Butyl Acetate = 1)	Slower than ether
Solubility in Water	N/A	pH	N/A
Appearance and Odor— White Caulk, No o	dor	VOC%	3.00000%
Flash Point (Method Used): Flashpoint below 73°F Auto - Ignition Temperature: N/A		Lower Flammability Level: N/A	Upper Flammability Level: N/A

Section 10 ~ Stability and Reactivity

Section 10 ~ St	tability and	Reactivity					
Stability: Unst	stable	Stable 🔀	Conditions to Avoid	l – High temperatures	Hazardous Polymerization:	May Occur	Will Not Occur
Incompatibility (Materials to Avoid) – N/A			Hazardous Decomposition or Byproducts	- In fire, will decompo	ose to carbon dioxide,	carbon monoxide.	

N/A

Section 11 ~ Toxicological Information

Information on toxicological effects

Acute toxicity: Inhalation: effect of overexposure includes irritation of respiratory tract, headache, dizziness, nausea, and loss of coordination. Extreme overexposure may result in unconsciousness and possibly death.

Overexposure will cause defatting Skin corrosion/irritation: Serious eye damage/eye irritation: Overexposure will cause redness and burning sensation. of skin. Causes skin irritation

Respiratory sensitization: N/A Skin sensitization: Germ cell mutagenicity N/A Carcinogenicity N/A Specific target organ toxicity - single exposure Reproductive toxicity

Specific target organ toxicity - repeated exposure N/A

Aspiration hazard - N/A

Section 12 ~ Ecological Information

Toxicity - N/A

Persistence and degradability: N/A Bioaccumulative potential: N/A

Mobility in soil: N/A

Other adverse effects:

N/A

Section 13 ~ Disposal Considerations

Disposal instructions: Water Disposal - Under RCRA, it is the responsibility of the user of the product, to determine at the time of disposal whether the product meets RCRA criteria for hazardous waste. Waste management should be in full compliance with federal, state, and local laws. Empty containers retain product residue which may exhibit hazards of material, therefore do not pressurize, cut, glaze, weld or use for any other purposes. Return drums to reclamation centers for proper cleaning and reuse

				1 480 5 51 5
Section 14 ~ Transport Infor	mation			
US Depart. of Transportation (DOT)	Consumer Commodity, ORM-I)		
Water Transportation (IMDG)	Consumer Commodity, ORM-I)		
Air Transportation (IATA)	Consumer Commodity, ORM-I)		
Special precautions for user: Read sa	fety instructions, SDS and emergency	procedures bet	fore handling. Read safe	ety instructions, SDS and emergency procedures before handling.
Section 15 ~ Regulatory Info	rmation			
US federal Regulations:				
Chemical name	CAS number		% by wt.	Regulation List
Methyltriacetoxysilane	4253-34-3		2% - 4%	SARA312, TSCA
Silica, Amorphous	7631-86-9		6% - 12%	SARA312, TSCA, OSHA
Ethyltriacetoxysilane	17689-77-9		2% - 4%	SARA312, TSCA
Mineral Seal Oil	64742-46-7		2% - 4%	SARA312, TSCA, OSHA
Methyl Siloxane Linear/Cyclic	70131-67-8		52% - 92%	SARA312, TSCA
Section 16 ~ Other Informati	ion			
	NFPA	HMIS		Key
HEALTH	1	1		4= Severe
FLAMMABILITY	1	1		3= Serious
REACTIVITY	0	0		2= Moderate

Disclaimer: To the best of our knowledge, the information contained herein is accurate. However, neither the above named supplier nor any of its subsidiaries assumes any liability whatsoever for the accuracy or completeness of the information contained herein. Final determination of suitability of any material is the sole responsibility of the user. All materials may present unknown hazards and should be used with caution. Although certain hazards are described herein; we cannot guarantee that these are the only hazards that exist. The above information pertains to this product as currently formulated, and is based on the information available at this time. Addition of reducers or other additives to this product may substantially alter the composition and hazards of the product. Since conditions of use are outside our control, we make no warranties, express or implied, and assume no liability in connection with any use of this information.

1=

0=

Slight

Minimal

OTHER/PROTECTION